




## 2018年3月16日实验室安全与环保检查情况汇总

楼名/房间	安全隐患	整改情况	整改前	整改后
学院附楼	冰箱上有杂物	已提醒		
学院附楼	冰箱上有杂物	已提醒		

<p>学院附楼</p>	<p>大功率用电器未接墙</p>	<p>已提醒</p>		
<p>学院附楼</p>	<p>线板接多个大功率用电器</p>	<p>已提醒</p>		

<p>学院楼</p>	<p>冰箱上放微波炉</p>	<p>已提醒</p>		
<p>学院楼</p>	<p>废液堆积</p>	<p>已提醒</p>		

西四教	插线板连接大功率设备	已提醒		
学院楼	烘箱放在木质箱子上	已提醒		

<p>西四教 230</p>	<p>烘箱隔板为木板</p>	<p>已整改</p>	 A photograph showing the interior of a white oven. A wooden shelf is placed inside, which is not a standard metal component. The oven door is partially open, and the interior is brightly lit.	 A close-up photograph of the wooden shelf mentioned in the text. The wood is dark and appears to be a natural material, possibly plywood or a similar composite material, which is not suitable for use as an oven shelf due to fire and chemical risks.
<p>西四教 428</p>	<p>插座在通风橱内</p>	<p>已整改</p>	 A photograph of a laboratory bench area. Several pieces of equipment are visible, including what looks like a water filtration system or a similar apparatus with multiple filters and tubes. The area is cluttered with various items, and the background shows a typical laboratory setting.	 A photograph showing a white power strip plugged into a wall outlet on a laboratory bench. The power strip is connected to several devices, including a large, round, white container (possibly a water dispenser or a specialized piece of equipment) and other electronic devices. The power strip is placed on the bench surface, which is not a safe practice.

<p>西四教 424</p>	<p>钢瓶使用时未固定</p>	<p>已整改</p>		
<p>西四教 427</p>	<p>钢瓶使用时未用铁链固定</p>	<p>已整改</p>		

